
## Citizen Monitors; Help or Hindrance


A Case Study from Southwestern West Virginia

## Site Location and History






Tom Scholl Sr. mined 2 seams (tan) in 1972 & caused acid mine drainage to this day in Kan. Fk. tributaries...



After the 1977 SMCRA passed, Tom Scholl Jr. opened the Rush Ck. & Rush Ck.#2 Mines, causing further amd.

	<b>⊭</b> H 6.5	eH 6.0	pH 5.5	<b>⊭H 5</b> .0	<b>#</b> H 4.5	<b>≓H 4</b> .0
TROUT						
BASS						
PERCH						
FROGS						
SALAMANDERS						
CLAMS						
CRAYFISH		ı				
SNAILS						
MAYFLY						

http://www.epa.gov/acidrain/images/waterspecies.gif



#### BASELINE SURFACE WATER ANALYSIS Avadorer 1-3B

Company Name | Kevetone Industries LLC dba Revelors: Development LLC |
Mine Name | KD7 Surface Mine

Laboratory Name Stradard Laboratories

Sargit			Hou.	Total Hot	Minem	Tom	Total	Total			Sec.			Dis	I Other
LD	Date	HH	CD	Acidny	Acidity	Alabrity	Fig	Mr	TES	TOS	Cond	304	AL.	.61	1
No	Sampled		Or Com-	CaCCO	CpCI:G	Carros	oper	pptn	Stru	\$Eur	mining	bon	Ppm	Ppm	Se
UMLB-2 BASELINE SITE	12/19/2007	5.8	18	4	- 0	5	0.09	0.15	- 1	152	288	125	0.07	< 05	
UMLB-2 BASELINE SITE	1/8/2908	5.8	- 4		.0	4	0.65	0.03	1	190	241	107	< 65	× 05	1
VIALBO BASELINE SITE	1/21/2008	5.1	16	15	- 0	5	0.98	0.05	1.	157	226	109	0.95	<.05	-
UMLB-1 BASELINE SITE	3/24/2008	6	64	7	0	3	0.06	0,07	2	136	13/2	43	0.1	<.05	1
UMLB-2 BASELINE SITE	4/3/2008	5.1	39		- 0		0.7	15	- 1	KI-	-1500	67	0.49	<.08	+
UMLB 2 BASELINE SITE	4/24/2008	6	27	_ 7	7		0	-		102	198	87	-0.09	C05	1
UMLB 2 BASELINE SITE	±/7/2008	E	0 1			3	0			121	101	03	< 05	5.05	+
UMLD-2 BASELINE SITE	6/26/2008	5.9	1 3				0.		45	568	690	381	0.33	0.04	+
UMLB-2 BASELINE SITE	7/29/2008		SIF							2000	-	301	16.57	9.04	-
UMLB 2 BASELINE SITE	0/24/2008		NE												-
UMLB 2 BASELINE SITE	11/20/2006	5.7	potled	Q.			0.39	9,07			188	94	~05	5,05	1
UMER 2 BASELINE SITE	1/16/2000	5.7	from			1	4.24	- 373			100	744	~0.0	5/00	+
UMLB-2 BASELINE SITE	2/19/2000	5.8	4				< 05				100	944	<.05	<.05	+
UMLB-1 BASELINE SITE	3/6/2009	6.1	37	i	0		0.12	Δ1	1		93	39.	D.06	<.05	+
UMLB-Z BASELINE SITE	5/8/08/09		45	- 5	0	3	5.2	0.22	1	279	278	172	30s		1
DMLB-2 BASELINE SITE	6/8/2000	50	751	11:-1	0	5	539	0.22	- 13	708			0.36	< 05	-
UMLB-2 BASELINE SITE	5/17/2009	5.5	247	<1	0	4	0.34	0.41	3	134	145	62		= 0.5	
DMLB-2 BASELINE SITE	7/4/1000	0.1	22	-[3-	- 0	4	0.25	9.51	3	340	The second second	95	0.29	<.05	200
UMLB-2 BASELINE SITE	7/15/2009	fr	48	177	- 0	4	0.25	6.43	- 1	112	416	222	0.15	-0.05	9.90
UMLB-2 BASELINE SITE	8/17/2009	0.0	39	TN/	_								0,26	~0.05	<30
UMLO-2 BASELINE SITE			- 25		11/		PI	cee	ecl	<b>ec</b>	291	161	0.34	0.15	<0.00
	8/27/2009	7.1	_								390	181-	0.05	01.	0.00
UMLO-2 DASHINE SITE	9/2/2009	58	9	- 6	D	5	0.2%	0.54	14	301	427	190	0.66	-0.05	OD
UMLO-2 BASELINE SITE	9/(5/2009	7.4	NF		-	1	40			-			-		-
	9/24/2009	6,8	9		9		140	no	0 14		036	187	0.06	<0.65	<0.0
UMLD O BASELINE SITE	10/6/2009	6,8	8		0		sta	nd	ar	ds	538 570 527 540	283	0.01	<0.05	<0.00
UMLD-2 BASELINE SITE	10/21/2009	7	9	<1		5	0.1	0.39	1		570	3)7	<0.03	<0.05	<0.00
UMLB 2 BASELING SITE	11/2/2009	7.1	19	<1	0	. 5	9.06	0.29	1	420	527	207	<0.05	40.05	₹0.00
UMLB 3 BASELING SITE	11/16/2009	7.1	8	- 3	0	- 4	8,06	0.14	1	368		272	-0.02	40.00	<0.00
UMLB-2 RASELING SITE	12/16/2009	6.9	10	- ल	0		6.(1)	0.22	. 3	192	268	113	0.08	-0.05	<9.09
UNILB-2 BASELINE SITE	12/28/2000	6.8	12	<	0		01	0.15	-8	111	136	- 55	0,05	<0.05	50.0
UME B-2 BASELINE SITE	1/13/00/10	6.6	114-	- 61	0		1		2	120	190	85	0.05	<0.05	-2.0
UMLB-2 BASELINE SITE	1/28/2010	65	41	<1 -	- 6				-1-	90	134	62	0.13	<0.05	-0,0
UMI.B. BAYELINE STIE	2/4/2010	7.5	23	29	0				- 2	105	185	82	80.0	<0.05	-20
UMLB-ZBASELINE SITE	3/24/2010	68	-24	11-1	0	Red	TH' 6	σ	1,1-	147	232	109	0.24	0.06	-00.00
UMLB-2 BASELINE SITE	3/3/2010	6.15	165	13		rcu	1 10	rg 🔳	2	236	340	114	0.45	6.34	-9.00
OMLB-2 BASELINE SITE	3/19/2010	EAR	190	7.1	_ 0				-22	163	250	100	0.23	< 0.05	-0.98
														7	
	Max	7.5	253,0	31.0	0.6	16,0	0.50	0.90	19.0	3680	896.0	3K) O	1149	0.24	0.00
	Average	5,4	50.5	11.5	0.0	4.0	6.51	0.32	3.3	218.9	301.9	144.4	0.14	0.13	0.00
	Miss	5.5	5,0	3.0	0.0	20	BDL	0.02	1.0	86 Q .	95.0	39.0	BOL	HIL	FALL

#### BASELINE SURPACE WATER ANALYSIS Attributed 3-3B

Compary Name: Keygone infusines LLC dia Keystone Gevelopment LLC

Mitte Name: KD2 Surface Mine

Laboratory Name Standard Laboratories

Sample	4.75	no.	Flaw	Intal Het	Minna	Total	Total	Tetal	I Call	Carrel	Spen		1	Dis	Oth
1.0	Date	PH	CN.	Acidity	Acidity	Alkalianity	Fe	Mr.	TSS	TOS	Cond	5.04	M	M	Se
Ms	Simpled		Gym	Ppm DaCC3	CaOU3	CaCO3	Mara	patri	ppin	hba	phosphics	PDm	Ppm	Ppm	pos
UKI-2 BASELINE SITE	1/24/2068	5 40	V0	111	-0	2 2	0.15	1.37	- 6	275	335	159		0.78	
UKE 1 HAS TIME SITE	4/3/2008	4.0	10	1.9	0		0,61	72	2	156	223	140	1.34	0.8	
UKF-2 BASELINE SITE	4/24/2008	57	14		- 0		0.14		1	192	313	140	0.7	0.63	
UKF-1 BASELINE SITE	5.7/2008	4.8	12		- 0	L	7.13	- 2	< 7	374	517	245	0.84	0.72	
UKF 1 BASELINE SITE	6/16/2008	8.6	1	<u> </u>	.0.	I	4.23	- /		723	894	A79	1.35	1.13	
LIKE-1 BASELINE SITE	7/29/2008		NE								-	1		- 11	
UKF 2 BASELINE BITE	9/34:2098		NE.												1
UKF-2 BASELINE BITE	11/20/2008	6	pooled	<1	Ø.	39	₹.05	<.01	-11		355	330	0.09	< 05	
UKF-2 BASELINE BITE	1/16/2009	-	finera												
UKF-Z BASELINE SITE	2/17/2009	5.7	7	15:	·D	-2	V.09	1.3	- 2		334	64	0.9	0.66	
JRF-2 BASELINE SITE	3/6/2009	3.7 3.3	7	13:	0.	<b>37</b>	0.10	7 .	. 2		200	130	0.75	0.57	
UKF-2 BASELINE SITE	5/26/2009		NF								-	1 1		- 100	
LIKE-2 BASELINE SITE	6/8/2009		NE												
IKF-Z BASELINE SITE	0/17/2009		NE							-		-			
JKF-1 BASHLINE SITE	7/9/2009		NT				-								
OKE J BASELINE SITE	77/14/2009		NE						-						1
UKF-I BASELINE SITE	3//1/2066		Ni Ni		₹-2	0.37	004			V(					
UKE-2 BASELINE SITE	8/27/2069		NI			ex	CCI						0.06		
UKE-I BASELINE SITE	9/2/2009		NE												
UKE-2 BASELINE SITE	40/15/2000		NF						1						
UKE 3 BASELINE SITE	9/24/2009	1	NF	-		at-	10/	I O M	2		1				
UKED BASELIME SITE	10/6/2060		NF		DH	Sta			UN						
UKF J BASELINE SITE	10/21/2009		NF												
UKF-I BASELINE SITE	11/3/2009		NF												
UKF 1 BARELINE BITE	11/16/2009		NF												
UKF-T BASELINE SITE	12/16/2004		NF									100			
UKF-2 BABELINE SITE	12/28/2009	6.7	2	< j	-0		0.32	10.0	В	182	743	104	0.2	-0.05	<0.00
UKF-2 BABELINE SITE	1/13/2010	6.5	2	<1	- 0		0.5	-0.02	3	239	118	21	-0.05	<0.05	-0.0
UKF-2 BABELINE SITE	1/28/2010	67	3	<).	0				20	140	192	RS	1.7	0.09	<0.00
UKE-2 BASELINE SITE	24/2010	7.2	3	16	0				2	155	145	04	0.3	<0.05	<0.00
UKF Z BASELINE SITE	2/24/2010	-	2	<1	0	Rec		$\alpha$	72	184	788	101	6.32	<0,05	49,00
UKE-2 BASHLINE SITE	3/3/2010	5.45	- 31	21	0	NEU		ag	1	320	476	774	1,66	43.	10.00
DKF-2 BASELINE SITE	3/19/2010	5.51	44	58	0				3	308	464	120	1.8	15	<0.00
	Mas:	7.2	47,0	51.0	0,0	500	2.0	50	22.0	728 0	884.0	475.0	1.3	1.5	0.00
	Average	5.8	15.6	20.5	0.0	0.9	0.4	14	54	270.9	381.5	182.3	0.8	0.8	0,00
	Man	4.8	20	BDC	0.0	7.0	BDL	BDL	BDI.	140.0	102.6	98.0	BDI.	BDL	BD

# Rush Creek Mine (RCM) records available to DMR from 5/2001 to 1/2013 when staff reviewed the KD#2 permit application

• Tom Scholl (mine permittee/owner) was cited for 23 violations, with 13 notices of violation (NOV's) and one cessation order issued for problems related to sediment control, water quality, or the hydrologic balance at that mine.

Rush Creek #2 Mine (RCM#2) records available to DMR from 12/2007 through 1/2013 when staff reviewed the KD#2 permit application

• Tom Scholl (mine permittee/owner) was issued 5 NOV's related to water and sediment control issues through January 2013 (two for sediment control problems, two for effluent limit violations, and one for failure to properly handle acid bearing/toxic materials). **Red Flag** 



Doug Wood photos




# KD2, Ten Seams of Acidic Coal: Same Old Problems, Different Permit

# The KD2 CHIA says...

• [p. 13] Any materials thought to have the potential for the production of a [sic] waters of an excessive acidic nature, excessive concentration of iron or a discharge high in selenium will be encapsulated "High and Dry" by alkaline material. This proposed Special Handling Plan appears to be adequate.

# The permit says...

- No acid production is expected
- No disch. other than precip-induced-only
- Permeable sediment ditches constructed of unconsoldiated, blasted rock and disturbed soil, will adequately prevent leakage of toxic materials
- Dilution by precip runoff will prevent upset in hydrological balance in stream
- Therefore, no need for biomonitoring



Feet	Material	pН	PyS	Net	Color	Notes
3.20	Mudstone	5.7		2.86	10YR8/4	
3.20	Mudstone	5.6		3.01	10YR7/8	
3.00	Mudstone	6.9		1.54	10YR7/2	Special handling (SH) due to Se
3.00	Mudstone	6.7		3.40	10YR7/3	SH due to Se
3.00	Mudstone	7.1		6.36	10YR7/3	
3.00	Shale	7.2		7.51	10YR7/2	
3.00	Shale	7.1		9.64	10YR7/2	
2.40	Shale	6.5		7.21	10YR7/2	SH due to Se
2.60	Shale	6.9		6.91	10YR6/2	
2.00	Shale	7.1		5.68	10YR6/2	
2.30	Shale	6.8		6.83	10YR6/1	
1.40*	Coal 7-Blk	3.3		-91.43	10YR2/1	SH due to Se & acid
3.40	Shale	5.6		-0.25	10YR6/1	
2.90	Mudstone	7.0		3.94	10YR7/1	
3.25	Mudstone	7.1		4.56	10YR7/2	
2.75	Shale	7.0		4.26	10YR7/6	
2.60	Shale	6.8		2.14	10YR7/8	T
4.40	Sandstone	6.3		7.15	10YR7/6	Targeted topsoil substitute
5.0	Sandstone	8.7		88.44	10YR7/4	Targeted topsoil substitute
5.0	Sandstone	8.3		16.99	10YR7/4	Targeted topsoil substitute
5.0	Sandstone	8.8		97.12	10YR7/6	Targeted topsoil substitute
5.0	Sandstone	8.5		4.54	10YR7/4	Targeted topsoil substitute
5.0	Sandstone	8.0		2.44	10YR7/6	Targeted topsoil substitute
5.0	Sandstone	7.8		1.44	10YR7/4	Targeted topsoil substitute
5.0	Sandstone	7.7		1.16 4.56	10YR7/8	Targeted topsoil substitute
2.80 0.80*	Sand/Shale Sandstone	7.1	1.06	-38.40	10YR6/4 10YR6/1	Targeted topsoil substitute Called "shale" in Attach.O-8. SH(Se,acid)
0.70	Coal 6-Blk	3.2	0.21	-12.24	101R0/1 10YR2/1	SH due to Se & acid
0.70	Shale	7.0	0.21	0.16	101R2/1 10YR5/1	SH due to Se & acid
0.90	Coal 6-Blk	4.6	0.49	-19.21	10TR3/1	SH due to Se & acid
1.65	Mudstone	6.4	0.43	-0.91	101R2/1 10YR6/1	SIT due to be de actu
2.65	Mudstone	6.9		0.91	10YR8/6	
5.00	Sandstone	6.9		1.09	10YR7/8	
5.00	Sandstone	7.0		0.66	10TR7/8	
1.00	Sandstone	7.2		0.41	10YR7/6	
1.70	Core loss			2	20220110	
2.30	Sandstone	7.1		0.79	10YR7/6	
5.00	Sandstone	7.1		1.36	10YR8/4	
5.00	Sandstone	7.0		1.66	10YR7/6	
5.00	Sandstone	6.4		1.86	10YR7/6	
5.00	Sandstone	5.4		-1.69	10YR7/1	
5.00*	Sandstone	5.4	0.07	-6.66	10YR7/1	SH due to acid
4.00*	Sandstone	5.1	0.10	-6.63	10YR7/1	SH due to acid
3.60	Sandstone	6.0		-3.53	10YR7/1	
2.90	Sandstone	6.6		-1.93	10YR6/1	
4.50*	Sandstone	7.1		-5.51	10YR6/4	SH due to acid

5.00	Sandstone	6.6		-2.16	10YR6/1	
5.00	Sandstone	7.7		4.34	10YR6/1	
5.00	Sandstone	7.4		4.36	10YR6/1	
5.00	Sandstone	7.1		0.39	10YR6/1	
5.00	Sandstone	7.4		1.51	10YR6/1	
4.90	Sandstone	7.0		-0.30	10YR6/1	
1.15	Coal 5-Blk	3.4	0.24	-21.40	10YR2/1	SH due to Se & acid
2.95*	Mudstone	7.5		-2.71	10YR5/1	SH due to Se & acid
1.00*	Shale/Coal	5.4	0.21	-21.91	10YR4/1	SH due to Se & acid
3.00	Shale	7.7		2.76	10YR5/1	
3.00	Shale	7.9		5.91	10YR5/1	
3.00	Shale	8.0		5.41	10YR5/1	
3.00	Mudstone	8.2		-0.41	10YR7/2	
4.00	Sandstone	7.7		3.29	10YR6/1	Targeted topsoil substitute
4.00	Sandstone	6.7		-0.51	10YR6/1	Targeted topsoil substitute
5.00	Sandstone	7.9		-0.64	10YR6/4	Targeted topsoil substitute
5.00	Sandstone	7.1		-0.54	10YR7/1	Targeted topsoil substitute
2.00	Sandstone	7.1		-2.49	10YR6/1	Targeted topsoil substitute
3.00	Sandstone/shale	7.6		4.25	10YR5/1	Targeted topsoil substitute
5.00	Sandstone	8.3		6.81	10YR6/2	Targeted topsoil substitute
5.00	Sandstone	8.3		7.49	10YR7/1	Targeted topsoil substitute
5.00	Sandstone	8.7		7.34	10YR7/1	Targeted topsoil substitute
0.45	Sandstone/coal	7.3		2.64	10YR5/1	Targeted topsoil substitute
4.55	Sandstone	8.0		5.21	10YR6/1	Targeted topsoil substitute
5.00	Sandstone	8.1		5.84	10YR6/2	Targeted topsoil substitute
4.00	Sandstone	8.0		5.41	10YR8/1	Targeted topsoil substitute
2.90	Sandstone	8.1		3.76	10YR8/1	Targeted topsoil substitute
0.50	Sandstone/Coal	8.4		87.68	10YR4/2	•
2.60	Sandstone	8.5		12.80	10YR7/2	
5.00	Sandstone	8.5		6.56	10YR7/1	
5.00	Sandstone	8.5		6.14	10YR7/1	
4.00	Sandstone	8.3		5.36	10YR7/1	
4.10	Sandstone	7.8		0.13	10YR7/1	
1.20	Shale	4.1	1.85	-70.24	10YR4/2	SH due to Se & acid
0.70	Coal, UprStockton	3.3	2.08	-90.33	10YR2/1	SH due to Se & acid
1.60	Shale/Coal (U.S.)	4.2	0.53	-41.56	10YR4/2	SH due to Se & acid
3.25	Coal, UprStockton	4.3	0.45	-27.86	10YR2/1	SH due to Se & acid
3.15	Mudstone	7.0		-8.56	10YR5/1	SH due to Se & acid
2.00	Shale	7.5		0.84	10YR5/1	
3.00	Shale	7.8		3.54	10YR5/1	SH due to Se
0.20	Coal,LwrStockton	5.3	0.18	-13.33	10YR2/1	SH due to Se & acid
0.45	Carbolith, L.S.	6.8	0.18	-6.48	10YR3/2	
1.95	Coal,LwrStockton	5.8		-9.01		SH due to Se & acid
3.00	Mudstone	7.4		-0.86	10YR5/1	
3.00	Shale	7.5		3.61	10YR5/1	
3.40	Shale	8.1		6.49	10YR5/1	
5.00	Sandstone	8.2		7.59	10YR6/1	
5.00	Sandstone	8.2		7.21	10YR5/1	
5.00	Sandstone	8.8		48.44	10YR7/1	

5.00	Sandstone	8.8		57.19	10YR7/1	
5.00	Sandstone	8.6		20.66	10YR7/1	
3.30	Sandstone	8.2		3.84	10YR7/1	
0.90	Shale	7.2	0.25	-3.04	10YR5/1	SH due to Se
1.20	Coal,CoalburgR.	4.7	0.47	-28.46	10YR2/1	
1.25	Shale	8.4		-4.39	10YR4/1	SH due to Se
0.35	Coal,CoalburgR.	5.1	0.14	-23.28	10YR2/1	SH due to Se
3.00	Shale	8.1		10.29	10YR6/1	SH due to Se
2.00	Shale	8.3		10.56	10YR6/1	
3.30	Sandstone	8.1		9.14	10YR7/1	
1.20	Shale	8.0		4.46	10YR6/1	SH due to Se
2.65	Coal, UpCoalburg	5.7	0.10	-8.65	10YR2/1	SH due to Se & acid
2.25	Shale	6.8		-3.15	10YR5/1	
1.70	Coal,LCoalburg	6.5	0.16	-5.58	10YR2/1	
0.22	Shale	6.6	0.10	-0.30	10YR5/1	
0.30	Coal,LCoalburg	3.9	0.16	-13.40	10YR2/1	
0.45	Shale	7.0	0.10	1.98	10YR5/1	
0.35	Coal,LCoalburg	4.9		-20.75	10YR2/1	
3.00	Shale	6.8		-0.44	10YR5/1	SAL SIGN TO BE BUILD
2.58	Shale	8.0		2.86	10TR3/1	
3.00	Shale	8.0		3.89	10TR7/2	
3.00	Shale	7.7		1.89	10YR6/1	
3.00	Shale	8.2		4.26	10YR6/1	
1.20	Shale	8.2		2.94	10YR7/2	
3.00	Shale	8.1		9.79	10TR//2	
1.50	Coal, WinifredeR	7.0	0.07	-5.96	10YR2/1	SH due to Se & acid
5.00	Sandstone	8.1	0.07	-0.06		Targeted topsoil substitute
5.15	Sandstone	8.1		1.44		Targeted topsoil substitute
5.15	Sandstone	8.2		1.54		Targeted topsoil substitute
5.00	Sandstone	8.3		3.31		Targeted topsoil substitute
5.00	Sandstone	8.4		2.89	101R//1 10YR71	Targeted topsoil substitute
5.00	Sandstone	8.2		5.06	101R/1	
5.00	Sandstone	8.7		183.44		Targeted topsoil substitute
2.35	Sandstone	8.7		16.26	101R//2 10YR7/1	
1.20	Mudstone	8.4		5.51		Targeted topsoil substitute
2.45	Sandstone/Mudst	8.4		4.39		Targeted topsoil substitute  Targeted topsoil substitute
4.00		8.0		5.44		Targeted topsoil substitute
5.10	Sandstone Sandstone	7.8		2.84		Targeted topsoil substitute
0.15	Coal, Winifrede	7.3	0.08	-4.35	10YR2/1	
0.15		8.5	0.08		10YR2/1 10YR4/1	
	Mudstone Coal WinifrodoPF		0.10	-1.54 -14.31		SH due to Se
2.60	Coal, WinifredeBE	5.8	0.19		10YR2/1 10YR5/1	SH due to Se & acid
	Shale	6.9		1.14		
3.85	Sandstone	8.9		387.19	10YR6/1	
3.15	Sandstone	8.3		16.96	10YR6/1	
3.00	Shale	8.4		3.79	10YR5/1	

End

# On-the-ground problems in distinguishing toxic overburden from non-toxic overburden

- Despite careful planning, blasts often mix toxic with non-toxic
- Colors are often too similar to distinguish
- Color is not uniform through each stratum
- Neutralization potential/deficiency is not uniform through each stratum
- Accurate field testing is not possible

# Instructions to the dozer operator after a blast:

"Push the black stuff to the hoe for loading, then push the brownish-gray stuff into an isolation area and push the grayish-brown stuff over top of the brownish-gray stuff. That ought to satisfy the inspector."



Doug Wood photo

### FINE PARTICLE SEPARATION DEVICE




http://www.arthon.com/equipment/arthon/D10\_ARTHON\_C utOUT\_Rocks700.jpg

### Kanawha Forest Coalition

# Kanawha Forest Coalition Assessed the Situation and Took Action

- Poor permit engineering & complex geology guaranteed that WQ problems would worsen
- DMR reluctant to enforce narrative WQ criteria
- DMR Inspection/Enforcement is understaffed
- Inspectors are woefully under-trained & underequipped to adequately protect water resources
- Consulting firm proved itself untrustworthy
- Experts at DWWM were not officially engaged to help DMR...

- ...The new inspector was open to information generated by citizen monitors
- Many volunteers were eager to stop the nightmare from worsening
- Inspection guidelines required the inspector to respond within 24 hours of receipt of a complaint
- SOS program was available for training volunteers & for supplying some equipment
- Sampling equipment purchases were minimal & KFC had grant-writing capability & other talents




August 8, 2014 KFC Citizen complaint about billows of foam on Kanawha Fork

## DMR investigated foam complaint

Kevin Seagle photo




- -Significant rainfall the previous week
- -Rainfall within 24 hours of stream sampling
- -Higher stream flows did not adequately dilute discharges
- -Found pH violations (permit & WQ) & high conductivity



...shared outlets, ignored KD2 O-15 & 14

# September 4, 2014 result of investigation

- Outlet 22 pH = 3.20
- Inspector Casto issued NOV
- Permittee/Operator set up inadequate, manual NaOH drip



### Road rock fill built 2008 & 2009. Connects the Rush Creek & RC#2 Mines.



# Title 38 Legislative Rule, Series 2 West Virginia Surface Mining Reclamation Rule

- The road was constructed in a manner that violates Performance Standard 4.7.a.5.
- "4.7.a. Each road shall be located, designed, constructed, reconstructed, used, maintained, and reclaimed so as to: [...]"
- "4.7.a.5. Neither cause nor contribute to, directly or indirectly, the violation of State or Federal water quality standards applicable to receiving waters"


#### BASELINE SURPACE WATER ANALYSIS Attachment J-JB

Compary Name: Keygone industries LLL dis Keystone Liewiopmen LLL

Mitte Name: KD2 Surface Mine

Latroniory Name Standard Laboratories


Sample	1.00	100	Flaw	Intal Het	Minual	Total	Total	Tatal	Local I		Spep			Die	Other
I.D	Date	PH:	CIV.	Acidity	Acidity	Alkatority	Fe	Mr.	TSS	TOS	Cond	5.04	M	Al	Se
Als:	Simpled		Or Gem	Ppm DaCC3	CaOO3	C#CO3	Mara	patri	ppin	pps	phosphic	PD:	Ppm	Ppm	pon
UKI-2 BASELINE SITE	3/24/2068	1.5	VD	111	-0	2	6.15	1.37	6	275	335	159		0.78	
UKE 2 HAS I INE SITE	4/3/20098	4.0	10	1.1	0	1	0,61	1.32	2	156	223	140	1.34	0.8	
UKF-2 BASELINE SITE	4/24/2008	57	14	13	- 0	2	0.14	1.12	1	192	313	140	0.7	0.63	
UKF-2 BASELINE SITE	5/7/2008	4.8									517	245	0.84	0.72	
UKF 2 BASELINE SITE	6/26/2008	8.6		•	<b>T</b> 71	<b>D</b> 114			-		894	479	1.35	1.13	
LIKE-1 BASELINE SITE	7/29/2008		′	'ho		D#2	) h	000	Min		-	1			
UKF-2 BASELINE BITE	9/24/2008					Utt 4	4 N	ast							
UKF-2 BASELINE BITE	11/20/2008	6									353	530	0.09	< 05	
UKF-2 BASELINE BITE	1/16/2009	-				_								-	
UKF-Z BASELINE SITE	7/17/2009	3.7			OM	nn	in	TO		rht.	334	64	0.9	D.fin	
UKF-2 BASELINE SITE	3/6/2009	3.7	VV	U	all	npl		2 UZ	เนย		200	130	0.75	0.57	
UKF-2 BASELINE SITE	5/26/2009							•		<b>,</b> •	-	1			
LIKE-2 BASELINE SITE	6/8/2009					_	_	_							
TIKE-Z BASELINE SITE	00/17/2009			tha		rob			<b>~==4</b>		-	-			
LIKE-2 BASHLINE SITE	7/9/2009									,					
UKE-J BASELINE SITE	7/14/2009							<del></del>						-	1
UKEJ BASELINE SITE	3/17/2066														
COLUMN THE REAL PROPERTY AND ADDRESS OF A PERSON.															
LIKE-2 BASELINE SITE	8/27/2069				D,	1404	rr 🔎		100	4			0.06		
The second secon	8/27/2060 0/2/2000				R s	staf	if d	lid	no	t.			0.05		
UKE-2 BASELINE SITE UKE-2 BASELINE SITE UKE-2 BASELINE SITE	The second secon			M	Rs	staf	if c	lid	no	t.			0.05		
UKE-2 BASELINE SITE	9/2/2009 9/15/2000 9/24/2009			M	Rs	staf	ff c	lid	no	t.			0.06		
UKE-2 BASELINE SITE	9/3/2009 9/15/2000		NF	M	Rs	staf	ff c	lid	no	t.			0.06		
UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2005 10/21/2009		NF NF	M	Rs	staf	ff d	lid	no	<b>t.</b>			0.06		
DKE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 10/2/2009 11/2/2009		NF NF NF	M	Rs	staf	ff c	lid	no	t.			0.06		
DKE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/16/2009		NF NF NF NF	M	R s	staf	if d	lid	no	t.			0.06		
DKE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/16/2009 12/16/2004		NF NF NF NF	M	Rs	staf	if d	lid	no	t.					
UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/16/2009 12/16/2004 12/28/2005	6.7	NF NF NF NF NF	<]	0	staf	ef c	D.01	В	182	243	164	02	-0.05	
DKE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/16/2009 12/16/2004 12/28/2005 1/13/2010	6.5	NF NF NF NF NF 2	<u>v</u>	0	staf			8 3	182 239	118	121	02	-0.05	-0.00
DKE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 12/28/2009 1/15/2010 1/28/2010	6.5 6.7	NF NF NF NF NF 2 2	ड ड ड	0 0	staf		D.01	8 3 20	182 239 140	118 192	121 88	02 -0.05 1.71		<0.06
DKE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/16/2009 12/16/2004 12/28/2005 1/13/2010	65 67 72	NF NF NF NF NF 2	<u>v</u>	0 0		€.32 QS	D.01	8 3	182 239	118 192 145	121	02	-0.05	<0.06
DRE-2 BASELINE SITE UKE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 1/2/8/2003 1/2/8/2010 2/24/2010	6.5 6.7 7.2	MF NF NF NF NF 2 2 3	\$\forall \text{\$\pi\$}\$	0 0 0 0		€.32 QS	D.01	8 3 20	182 239 140 153 184	118 192	121 88	02 -0.05 1.71	-0.05 0.09	<0.06 <0.06 <0.06
DRE-2 BASELINE SITE URE-2 BASELINE SITE	9/24/2009 9/24/2009 9/24/2009 10/6/2009 11/2/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 1/1/16/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009	6.5 6.7 7.2 7	MF NF NF NF NF 2 2 3	∀] ∀] ∀ 16 ∀]	0 0 0 0	Red	€.32 QS	D.01	8 3 20 2	182 239 140 153	118 192 145	21   B8   04	02 -0.05 1.71 0.3	→0.05 0.09 ≪0.05	-0.06 -0.06 -0.06
DRE-2 BASELINE SITE URE-2 BASELINE SITE	9/2/2009 9/15/2009 9/24/2009 10/6/2009 11/2/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 1/2/8/2003 1/2/8/2010 2/24/2010	6.5 6.7 7.2	MF NF NF NF NF 2 2 3	\$\forall \text{\$\pi\$}\$	0 0 0 0		€.32 QS	D.01	8 3 20 2	182 239 140 153 184	118 192 145 268	21 88 04	02 -0.05 1.71 0.3 0.32	<0.05 0.09 <0.05 <0.05	-0.06 -0.00 -0.06 -0.06 -0.06
UKF-2 BASELINE SITE	9/24/2009 9/24/2009 9/24/2009 10/6/2009 11/2/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 1/1/16/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009	6.5 6.7 7.2 7	MF NF NF NF NF 2 2 3	∀] ∀] ∀ 16 ∀]	0 0 0 0		€.32 QS	D.01	8 3 20 2	182 239 140 153 184 339	118 192 145 268 476	21   88   04   101   174	02 -0.05 9.71 0.3 0.32	<0.05 0.09 ≪0.05 ≪0.05 143	-0.06 -0.06 -0.06 -0.06 -0.06
DRE-2 BASELINE SITE URE-2 BASELINE SITE	9/24/2009 9/24/2009 9/24/2009 10/6/2009 11/2/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 1/1/16/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009 1/1/28/2009	6.5 6.7 7.2 7	MF NF NF NF NF 2 2 3	∀] ∀] ∀ 16 ∀]	0 0 0 0		€.32 QS	ag	8 3 20 2 2 22 2 1 3	182 239 140 153 184 320 338	116 192 145 268 476 464	21   88   04   101   214   220	02 -0.05 1.71 0.3 0.32 1,66 1.8	<ul> <li>-0.05</li> <li>0.09</li> <li>-0.03</li> <li>-0.05</li> <li>-1.05</li> <li>1.43</li> <li>1.5</li> </ul>	-0.06 -0.00 -0.00 -0.00 -0.00
DRE-2 BASELINE SITE UKE-2 BASELINE SITE	9/24/2009 9/24/2009 10/6/2009 10/6/2009 11/2/2009 11/2/2009 11/16/2009 12/16/2009 12/16/2009 1/2/8/2009 1/13/2010 2/4/2010 2/4/2010 3/19/2010	6.5 6.7 7.2 7 5.45 5.51	NF NF NF NF NF 2 2 3 3 2 4 4	<  <  <  5) 16 <  21 58	0 0 0 0 0 0 0 0 0 0	Rec	•.32 •.5	D.01	8 3 20 2	182 239 140 153 184 339	118 192 145 268 476	21   88   04   101   174	02 -0.05 9.71 0.3 0.32	<0.05 0.09 ≪0.05 ≪0.05 143	-0.06 -0.06 -0.06 -0.00 -0.00 -0.00




Rock fill at head of Kanawha Fork with no sediment/water control structures



Rock fill is crammed with acid-producing coals, gray shales, and other nasties.



Permeable road surface and sediment ditch allow water into the toxic rock fill



April 7, 2015 DMR follow-up sampling accompanied by the citizen who called attention to the rock fill source of acid at the very head of Kanawha Fork

- Rock fill hillside seep pH = 4.4
- Kanawha Fk downstream pH = 4.7
- As of 3/22/2016, no NOVs issued and no further sampling by DMR




## Result: NOV for off-site damages to tributary






## April 4, 2015 KFC sampling

- Outlet 20 pH = 4.5
- Not enough NaOH






### April 28, 2015 KFC Bioassessment


STREAM NAME	MILE POINT	WVSCI	WVSCI NARRATIVE SCORE	WVSCI PCT OF THRESHOLD	SEAGION	GLIMPSS CHIRO FAMILY	GLIMPSS CF NARRATIVE SCORE	GLIMPSS CF PCT OF THRESHOLD	GLIMPSS CHIRO GENUS	GLIMPSS CG NARRATIVE SCORE	GLIMPS CG PCT OF THRESHOLD	SOS HABITAT SCORE
Middlelick Branch	2.3	94	Unimpaired- Very Good	137.69	Spring Mountains	80.86	Unimpaired- Excellent	158.54	80.60	Unimpaired- Excellent	152.07	59
Middlelick Branch	1.6	85	Unimpaired- Very Good	125.21	Spring Mountains	59.64	Unimpaired- Good	116.95	60.76	Unimpaired- Good	114.64	53
Kanawha Fork	2.4	5X	Impaired- Slightly	85.33	Spring Mountains	24.62	Impaired- Moderately	48.27	25.75	Impaired- Moderately	48.58	51






### May 3, 2015 leachate from SD-1 of O-21









## May 3, 2015 undisturbed headwater







Contrast UT-RCM-21 with UT-KD2-1 to understand stream chemistry of acid mine seepage

## Contrasting streams

### Undisturbed headwater

- pH at E/I point = 5.33
- Cond. = **47.6**  $\mu$ S/cm
- Mayfly, crayfish, & salamander survive.
- pH at mouth = 6.67
- Cond. = **59.3**  $\mu$ S/cm
- Enough natural alkalinity to overcome the low pH just a few hundred meters downstream. No foam.

### Mine leachate headwater

- pH at E/I point = 4.24
- Cond. =  $1,093 \mu S/cm$
- Mayfly, crayfish, & salamander die.
- pH at mouth = 5.19
- Cond. =  $413 \mu S/cm$
- Alkalinity inadequate for acid burden. Foam forms in receiving stream. Mayfly & crayfish die. Salamander survival is not assured due to high metal & ion levels.



west virginia department of environmental protection

Division of Mining and Reclamation 601 57th Street, Charleston, WV 25304 Phone: (304) 926-0490 Fax: (304) 926-0456

Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary dep.wv.gov

June 15, 2015

Keystone Industries, LLC DBA Keystone Development, LLC 1915 Wigmore Street Jacksonville, FL 32206

Re: Permit No. S-3006-09 / SC #1413

#### Dear Operator:

You are hereby notified that your mining operation, Permit Number S-3006-09 for 413.80 acre(s) near Marmet in Kanawha County, West Virginia, is or has been in violation of Article 3, Chapter 22 and the rules and regulations adopted thereunder as follows:

- Permittee/Operator failed to conduct mining as per the approved plan NOV 014 Cessation Order 018 issued for failure to abate NOV 014


Now therefore, take notice as required by Section 17, Article 3 Chapter 22 of the Code of West Virginia, that the Secretary has determined a pattern of violations exists on the aforesaid permit and you are ORDERED to show cause, if any, why the above referenced permit should not be suspended or revoked. You have thirty days from receipt of this Order to request a hearing from the Secretary of the Department of Environmental Protection to show cause why this permit should not be suspended or revoked, or request that a Consent Order be entered into with the Department. Failure to respond to this Order shall result in permit suspension or revocation and/or declaration of forfeiture of the bond for this permit. Provided that a show cause hearing is requested, it shall be conducted by the Department of Environmental Protection.

Please direct all correspondence to the attention of Michele Sturey, WVDEP, Division of Mining & Reclamation 601 57th St., Charleston, WV 25304.

cc: Phil Mooney, Environmental Inspector Supervisor Mark Casto, Environmental Inspector Pat Lewis, Assessment Officer

Promoting a healthy environment.

"[...] the Secretary has determined a pattern of violations exists on the aforesaid permit and you are ordered to show cause, if any, why the above referenced permit should not be suspended or revoked."



## KFC's assistance to the DMR

- Foam complaints triggered findings of frequent and many AMD discharges
- Suspicion led to discovery of data falsification by the consultant
- Upward stream investigations found off-site damages, foam sources, acid leachate, & road fill acid source ...

- ... Proved that toxic overburden cannot be effectively isolated in complex acidic geology using current technologies
- Proved that manually adjusted NaOH drip cannot effectively treat widely varying flow
- Sampling effort triggered responses from DMR inspector that led to 5 show-cause orders on 3 mines & limited the perpetual acid mine drainage footprint at KD2 to 83 acres instead of the originally planned 413 acres ...

## ... disproved these permit assumptions

- No acid production expected
- No discharges other than precipitation-only
- Permeable sediment ditches constructed of unconsoldiated, blasted rock and disturbed soil, will adequately prevent leakage of toxic materials
- Rainfall dilution will prevent upset in hydrological balance in stream
- Therefore, no need for biomonitoring

"Like a fiend with his dope and a drunkard his wine, a man will have lu\$t for the lure of the mines."


- Merle Travis, It's dark as a dungeon way down in the mine, first recorded August 8, 1946.


# Feb. 5, 2014 KD#2 Mine Cumulative Hydrologic Impact Assessment (CHIA), DMR geologist wrote (bracketed words are not his)...

- [p. 14] The writer as an agent of the Department of Environmental Protection has used all the available information and assessed the hydrologic impacts of the proposed operation.
- [p. 2] To date, the author is unaware of any outstanding environmental problems. Elevated levels of traditional acid mine drainage (AMD), such as [...] low Ph, [sic] have not manifested themselves in the surrounding mine locations. Baseline water data tested within acceptable water quality standards (WQS).
- [p. 3] The applicant has a history of successfully managing these same ABA [Acid-Base Accounting] and selenium problems on the adjoining active mining permits. I see no reason to believe that this success will not continue
- [p. 8] To the best of the writer's knowledge the adjacent mine [RCM] is/ has been environmental [sic] successful. No adverse environmental conditions were noted at the time of Field Inspection. Therefore, I see no reason not to believe that the mining of S-3009-04 [KD#2] [will] lead to an[y] environmental problems.

# How the permit's special sampling requirement failed to protect streams

- Incorrect assumption of no pollution due to dilution
- Permittee failed to conduct/agency failed to enforce special sampling during first 11 months, and almost never since
- Permittee targeted sampling primarily during no-flow periods
- Permittee/Consultant falsified no-flow data
- Permit stipulation of sampling after 0.3 inches of rain in 24-hour period allowed consultant to sample before outlets discharged and to inadequately sample first-flush and runoff taper phenomena (greatest potential pollution)
- First-flush pushes metal precipitates and acid out of sediment control ditches before dilution can work
- Runoff taper period leaches acid in large quantities from the ditches into the receiving streams





## Assurances from geology?

From Attachment O-8 of the revised Material Handling Plan:

"Experience with Acid-Base Accounting (ABA) has shown that overburden layers which provide values greater than 5 tons per 1000 tons net deficient in neutralizing potential PRODUCE ACID, while values greater than 20 tons per 1000 tons net excess in neutralizing potential USUALLY produce alkaline discharge. Overburden layers between 0 and 5 net deficient or less than 20 tons in net excess MAY PRODUCE ACID or alkaline drainage or they may be neutral producing neither alkalinity nor acidity. (Where little or no pyrite exists, even with low amounts of neutralizing potential, little acid will be produced.)"

## What's the prognosis?

- Reclamation is entrusted to the same permittee (Tom Scholl) who caused perpetual acid mine drainage at the adjacent two mines
- Reclamation plan is approved and overseen by the same agency that approved the faulty permit
- Perpetual acid mine drainage already at KD#2 is worsening as reclamation progresses
- Complex geology combined with ignorance = Inability of Tom Scholl to appropriately blend non-toxic with toxic overburden or to adequately cover toxic with non-toxic overburden
- Inability of DMR staff to adequately guide Tom Scholl's blasters and dozers in distinguishing toxic from non-toxic blasted rock
- Perpetual acid runoff/leachate from the rock road fill between RCM and RCM#2 with no treatment whatsoever considered by the DMR
- Kanawha Fork and tribs of Middlelick Branch will never recover

## And yet...

• The mine spoil surrounding the sediment ditches leaches acid, causing at least 3 of the 4 shared sediment ditches to leach acid, causing three shared outlets (20, 22, & 23) to discharge acid, & causing KD#2 outlets 14 & 15 to discharge acid & their sediment ditches to leach acid resulting in permit violations & WQ standards violations. Handoperated NaOH drips are now used to neutralize discharges (inadequately so), but the drip treatment fails to neutralize the acid leaching from the sediment ditches into the soil & groundwater.

